

**Brandt's Appliance Service**  
**6880 US Highway 1**  
**Vero Beach, FL. 32967**  
**7725625759 Voice, 7725628120 Fax**

Name, Address and Telephone Numbers for the Paying Party  
**REAHARD, RALPH**  
**413 NW CHIPSHOT # 413**  
**PORT SAINT LUCIE, FL 34986**  
**813-541-6536**

Invoice Number  
**231772**

Date Order Taken and Completed  
**2/12/18**  
**2/19/18**

Name, Address and Telephone Numbers for the Service Location (if different from above)

Item Make and Type  
**REAL FYRE**  
**FIRE TABLE**

Purchase Date

Description of Symptoms and/or Customer's Request  
**REAL FYRE NO GAS GOING TO UNIT \$99.00 / DIMPLEX - SHOW HOW TO USE \$49.50**

Model and Serial Numbers  
**OCBE-34P**  
**564925**

Service Performed  
**FIRE TALBE NEEDS A THERMAL COUPLEUSED A 2 PRONG SPARK MODWANTS QUOTE FOR VENTING TABLE (MAYBE 30 MINUTE TO DO SO)HAS A EVO AFFINITY 30G (SERIAL:2027)NEEDS AN IGNITION MODULE; JOB CMLPTD, Customer paid \$438.09 via Bankcard**

Parts Used

1	241-SV-30-1	THERMOCOUPLE OCBE-34P	23.00	23.00
1	2 PRONG SPARK		24.99	24.99
1	VENTING TABLE		100.00	100.00
	EVO AFFINITY 30G	SERIAL:2027		
1	IGNITION MODULE	IGNITION MODULE EVO AFFINITY 30G	59.99	59.99
1	SHIPPING		12.95	12.95
1	FIRE TABLE	SERVICE CALL	99.00	99.00
1	EVO SERVICE CALL		49.50	49.50
1	LABOR		40.00	40.00

Record of Times at Location  
**TK 2/19 MON 9:30 11:34 02:04**

Payments Received  
**2/28/18 BankcardRef#1005904826 \$438.09**  
**BALANCE DUE 0.00**

Parts Total  
**409.43**

Service Call

Labor

Sales Tax  
**28.66**

Invoice Total  
**438.09**

Technician's Signature  
**Tim K.**

Customer Signature